EXHIBIT 21

09-50026-mg Doc 13027-21 Filed 12/16/14 Entered 12/16/14 17:20:07 Exhibit 21 Pg 2 of 3

TECHNICAL ASSISTANCE CENTER

**** GM RESTRICTED ****

Privacy

2004

AG

CA

032494

Saturn

Case No:	08578253	VIN:
Date Opened:	20051110	Model Year:
Date Closed:	12/31/2010	Model Series:
Dealer Code:	S121708	Mileage:
Dealer Name:	McLean Automotive, IEl Cajon	Dealer State:
Dealer Phone:	6194447200	Division:
	RACT NOCRANK NOSTART STALL INTERM	HITTENT NO CODES FOUND
RESOLUTION AB		
UCC 1 DESCRIPA		
UCC-1 DESCRIPT UCC CODE 2	~	
UCC-2 DESCRIPT		
UCC CODE 3		
UCC-3 DESCRIPT		
11/10/2005 11:47:1	9 SBD Template - KILGER	
STRATEGY BASE	D DIAGNOSTICS	
3 Number of time	es in for the same condition	
3 Number of day.	s vehicle in dealership for same condition	
n Y/N Is the veh	icle modified/non-production accessories (List	
below)		
n SI Document L	D Number supplied by Dealer	
Caller's name (Firs	t, Last, and Position)	
Privacy Tech		
Customer concern -	-	
No crank No start a	and vehicle stalls intermittently.	
Dealer comments/d	iagnosis -(DTC'S, Parts, Repairs, Duplicated, SI	
Search, Compare to	o like Vehicle?)	

Tech cannot duplicate the concerns and found no codes in system.

09-50026-mg Doc 13027-21 Filed 12/16/14 Entered 12/16/14 17:20:07 Exhibit 21 Pg 3 of 3

TECHNICAL ASSISTANCE CENTER

**** GM RESTRICTED ****

Case No: 08578253

VIN:

Privacy

Date Opened:

20051110

Model Year:

2004

Date Closed:

12/31/2010

Model Series:

AG

Dealer Code:

S121708

Mileage:

032494

Dealer Name:

McLean Automotive, IEl Cajon

Dealer State:

CA

Dealer Phone:

6194447200

Division:

Saturn

TAC recommendation -

Advised tech to perform bulletin 03-06-03-006A for this concern.

Advised tech on cases in the database where the ignition switch was replaced for this concern.

11/10/2005 11:47:19 History - KILGER